

































Nashik, Maharashtra, India

21/01/22 01:51 PM

Gangapur Road, Rambhoomi, Veer Sawarkar Nagar, Nashik, Maharashtra 422005, India Lat 20.011254° Long 73.753234°

GPS Map Camera



CENTRAL HINDU MILITARY EDUCATION SOCIETY, NASHIK

Bhonsala Bhavan, Rambhoomi, Dr. Moonje Marg, Nashik – 5 Phone No. 0253 – 2309600/01

CHMESND/20-21/ 919

Date: 03/2/2022

To.

SHRADDHA FIRE PROTECTION SYSTEMS PVT. LTD.

3B, Vrushali App., Near Mahatma Nagar Ground,

Near Banjara Hotel,

Mahatma Nagar, Nashik - 422005

Cell.: 7030907001

Sub:- Refilling of Fire Extinguisher cylinders

Dear 3ir,

With Reference to your quotation dated, 25 December 2020, we would like to place an order for supply of following materials as discussed during your personal interaction with concerned authority for supply of following material in respect of "C.H.M.E.Society Nashik"

The terms and condition of this order and necessary instructions regarding mode of dispatch, payment taxes etc. are mentioned below.

Sr. No.	Item Description	Qty.	Rate	
1	Refilling of ABC Type Fire Extinguishers ABC Type – 1.0 Kgs Capacity	1 No.	177/-	
2	Refilling of ABC Type Fire Extinguishers ABC Type – 2.0 Kgs Capacity	1 No.	212/-	
3	Refilling of ABC Type Fire Extinguishers ABC Type – 4.0 Kgs. Capacity	1 No.	472/-	
4	Refilling of ABC Type Fire Extinguishers ABC Type – 5 Kgs. Capacity	1 No.	531/-	
5	Refilling of ABC Type Fire Extinguishers ABC Type – 6.0 Kgs Capacity	1 No.	613/-	
6	Refilling of Co2 Type Fire Extinguishers Co2 Type – 2.0 Kgs Capacity	1 No.	212/-	
7	Refilling of Co2 Type Fire Extinguishers Co2 Type – 4.5 Kgs Capacity	1 No.	295/-	

Terms & Conditions:

- 1. Delivery within 6 days
- The vendor must ensure that the fire extinguisher cylinder collected for the purpose of refilling must be returned to the same unit.
- Proper cleaning of interior and exterior of fire extinguisher, polish the painted portion with wax polish, the brass/gun metal parts with metal polish, chromium plated parts with silver polish and plastic components to be thoroughly washed with soap solution and sun dried.

- 4. The vendor shall provide at least one training session to all units to the CHME Society staffs/ and security guards on operation and handling of fire extinguishers. Number of participants: as per present. Include both theory and practical demonstration of fire extinguisher. Each participant must get a hands-on experience of handling a fire extinguisher. Expertise must come from the vendor. Vendor can use expired fire extinguishers for the demonstration.
- 5. The vendor shall provide Training Certificate and Refilling Certificate to each unit individually.
- Checking of Nozzles, Port Hole, Vent Hole, Cap Assembly, Siphon Tube, Safety Pin/Clip, Discharge Pipe etc.
- 7. After refilling, paste inspection card to the body of Fire Extinguishers indicating the serial number, date of refilling, next date of refilling, due date for hydraulic testing, etc.
- Ensure that all joints are fully tightened and Nozzle, Vent Hole, etc are free of dust/dirt.
 Operating instructions of Fire Extinguishers are clearly legible and facing outward and in good visible condition.
- The vendor shall repair and refill the Fire Extinguisher free of cost within the warranty period of refill, if weight loss is noticed in the fire extinguishers which have been refilled.
- 10. Checking wall bracket/ fire stand of fire extinguishers
- 11. Replace old gas cartridge and extinguishing media of the fire extinguisher.
- 12. When fire extinguishers are taken for refilling, the vendor shall provide equal number & similar type of fire extinguishers in working condition as temporary replacement at no extra cost whatsoever till the refilled fire extinguishers are brought back and installed.
- 13. Replacement of small spares like rings/washers to be done at no extra cost.
- 14. Warranty: The re-filling of Fire Extinguishers shall have a warranty of 1 year from the date of refilling. The vendor shall provide for refilling of Fire Extinguisher(s) free of cost, if weight loss in noticed within the warranty period and replacement of Fire Extinguishers shall have to be provided in such a case.
- 15. Payment made give after delivery and successful installation.

16. Above Rates are inclusive of all taxes and transportation.

Central Hindu Military Education Society Nashik Division Nashik

Copy to: All Sub Units of C.H.M.E.Society

* Director, O.M. I. Nashik

Dr. Moonje Institute of Managemetn & Computer Studies Nashik

Pest Control Area (Aug 2022)

Sr.	Date	Institute Area	Room Count	Institutes Person Name & Sign	Pest Control Person Name & Sign	
		Ground Floor				
1		Old Director Cabin	1			
2		Old Chairman cabin	1			
3		Office	1			
4		MBA Marketing	1			
5		MBA prod. & material.	1		1	
6		MBA HR	1			
7		Faculty room	1			
8		Director Cabin	1			
9		Exam room	1		Presido sopación	
10		Store room	1			
11		MBA I	1			
12		Auditoriam hall	1	Deopole Solve		
13		MBA II	1			
14		Guest Room	1			
15		Chairman cabin	1			
16		Meeting room	1			
17	20.00.00	MBA II Int. bus.	1			
18	30-08-22	MBA II IT	1			
19		MBA Finance	1			
20		MBA Seminar	1			
21		Toilet Ladies	3			
22		Toilet Gents	3			
		First Floor				
23		Lab	4			
24		Tutorial room	2	Deepuk Bohul	y Pravio Sarawa	
25		Ladies room	1			
26		Placement & Edc cell	1			
27		MCA I	1			
28		MCA II	1			
29		Library	1		40 18 Thomas	
30		MCA III	1			
31		Audio visual room	1			
32		Server room	1			
33		Toilet Ladies	3			
34		Toilet Gents	3			
		Total	46			